

EL In-Place Inclinometer

56804199

Copyright ©2006 Durham Geo Slope Indicator. All Rights Reserved.

This equipment should be installed, maintained, and operated by technically qualified personnel. Any errors or omissions in data, or the interpretation of data, are not the responsibility of Slope Indicator Company. The information herein is subject to change without notification.

This document contains information that is proprietary to Slope Indicator company and is subject to return upon request. It is transmitted for the sole purpose of aiding the transaction of business between Slope Indicator Company and the recipient. All information, data, designs, and drawings contained herein are proprietary to and the property of Slope Indicator Company, and may not be reproduced or copied in any form, by photocopy or any other means, including disclosure to outside parties, directly or indirectly, without permission in writing from Slope Indicator Company.

SLOPE INDICATOR


12123 Harbour Reach Drive
Mukilteo, Washington, USA, 98275
Tel: 425-493-6200 Fax: 425-493-6250
E-mail: solutions@slope.com
Website: www.slopeindicator.com

Contents


| | |
|-------------------------------|----|
| Introduction..... | 1 |
| Pre-Assembly | 5 |
| Vertical Installation | 6 |
| Horizontal Installation | 11 |
| Manual Reading | 14 |
| Data Logging..... | 16 |
| Data Reduction..... | 18 |
| Removing Sensors..... | 23 |

Introduction

In-Place Inclinerometers



In vertical installations, one pair of casing grooves should be aligned with the expected direction of movement.



In horizontal installations, one pair of casing grooves must be aligned to vertical.

The in-place inclinometer system consists of inclinometer casing and a string of linked in-place inclinometer sensors.

The inclinometer casing provides access for subsurface measurements, controls the orientation of the sensors, and moves with the surrounding ground.



In vertical installations, the inclinometer casing is installed in a borehole that passes through a suspected zone of movement. One set of grooves is aligned in the expected direction of movement (downhill, for example).

In horizontal installations, inclinometer casing is typically installed in a trench. One set of grooves must be aligned to vertical, since the instrument is expected to monitor vertical movements (settlement or heave).


The string of linked sensors is positioned inside the casing to span the zone of movement. When the ground moves, the casing moves with it, changing the inclination of the sensors inside the casing.

Sensors for vertical installations measure inclination from vertical. Sensors for horizontal installations measure inclination from horizontal. Inclination measurements from the sensors are processed to provide displacement readings in mm of displacement for the gauge length of each sensor.



In most applications, sensors are connected to a data acquisition system and data processing is completed by a computer program.



IPI Sensor Components



Other Components



Gauge Tubing

Gauge tubing is typically ordered with the sensors. If gauge tubing is not supplied, check project specifications for required gauge length, and then follow the instructions below:

1. Choose stainless tubing that can accept tubing clamps. The standard tubing clamps have a minimum OD of 15.6 mm (0.615 inch) and expand to a maximum OD of 17.4 mm (0.685 inch).
2. Measure and mark the gauge tubing for the proper length:
tubing length = total gauge length – 550 mm (21.625 inch).
For example, you would cut tubing lengths of 1450 mm for a total gauge length of 2 meters.
3. Cut and deburr the gauge tubing. Check that tubing clamps fit inside.

Suspension Cable

Suspension cable, if used, is typically ordered with the system. The suspension kit contains hardware for 3/16 inch cable. The cable is 3/16 inch, 19 x 7, stainless steel aircraft cable.

Placement Tubing

Placement tubing, if used, is typically ordered with the system. If placement tubing is required, but not supplied, follow the instructions below.

1. Choose stainless tubing that can accept tubing clamps and couplings. The standard tubing clamps have a minimum OD of 15.6 mm (0.615 inch) and expand to a maximum OD of 17.4 mm (0.685 inch).
2. Deburr the gauge tubing and check that tubing clamps fit inside.
3. Use the coupling shown on previous page to join lengths of placement tubing.
4. Use in-line wheel assembly if placement tubing must be articulated.

Safety Cable

In vertical installations, you may find it useful to connect a safety cable to the bottom sensor to prevent accidental loss of the sensors.

Pre-Assembly


Introduction This chapter tells how to connect gauge tubing to the sensors. We do not recommend further pre-assembly. Sensors should be joined to other sensors only as they are installed downhole.

Tools

- Vice-grips to hold gauge tubing.
- Wrench to tighten tubing clamps.


Identify and Check Sensors

- Test each sensor. See “Manual Readings” for instructions.
- Write down the serial number and intended installation depth of each sensor.
- Check that wheels are firmly attached to sensors. Also check that the swivel clamp is attached to the wheel assembly of the bottom (farthest) sensor.
- Check that cable lengths are correct and attach sensor ID tags to ends of signal cables.
- Mark sensors for order of installation.



Attach Gauge Tubing to Each Sensor As you work, be careful not to bend or damage the wheel assembly as you work.

1. Remove the tubing clamp from the top of the sensor body.
2. Insert clamp into gauge tubing
3. Hold tubing and tighten clamp well.
4. Screw gauge tubing onto sensor body until sensor body and gauge tubing form a rigid unit.



Vertical Installation

- Overview**
1. Lay out sensors in order of installation.
 2. Insert the first sensor in the preferred set of grooves. The fixed wheel should point toward the expected direction of movement.
 3. Lower the sensor into the casing. Keep the top of the gauge tube accessible.
 4. Align the next sensor with the preferred set of grooves as in step 2, and connect it to the gauge tubing of the downhole sensor.
 5. Lower the sensors into the casing. Repeat steps 4 and 5 until all sensors have been installed.
 6. Prepare the suspension kit or the placement kit.
 7. Lower the sensors to their final location and terminate the top.



- Required Tools**
- Safety cable attached to bottom sensor to prevent loss of sensors down hole.
 - Vice grips (clamping pliers) for holding gauge tubing while connecting adjacent sensors.
 - Thin 17 mm wrench for tightening tubing clamps.
 - Tools for cable clamps or Allen wrench for securing top clamp.
 - Vinyl tape for securing cable to gauge tubing.

- Preparations**
1. Note serial number and position of each sensor.
 2. Lay out sensors in order of installation. We do not recommend pre-assembly of the string of sensors. Add sensors to the string one by one as you install them downhole.
 3. Keep cables coiled until sensor is installed.

- Removal**
- If it is necessary to remove sensors, take the following precautions:
- Never try to remove the assembled string of sensors. The weight and leverage of long gauge lengths make it very easy to damage the wheels.
 - Always disassemble the string, sensor by sensor. When removing each sensor, always clamp the gauge tubing of the downhole sensor to prevent it from twisting.

Install the Bottom Sensor


1. Attach safety line (nylon or wire rope) to bottom sensor. Secure the safety line.
2. Insert first (bottom) sensor in preferred set of grooves. The fixed wheel should point to the expected direction of movement. Check that the wheel has a swivel clamp.
3. Lower sensor into casing. Tape signal cable to gauge tubing. Use vice grips to clamp top of gauge tubing. Now the next sensor can be installed.



Install Next Sensor

Connect next sensor to the gauge tubing of the sensor below, as shown in the drawing. Continue adding sensors until the sensor string is complete. Keep the following points in mind:


- Do not allow the installed sensor to twist in the casing when you tighten the connection. Twisting can damage the wheels or pop them out of the grooves.
- When you lower the sensor into the casing, check that the fixed wheel is aligned in the proper direction.
- Tape cables neatly, so that they do not cross each other.



Install Top Wheel

Attach top wheel from suspension kit or placement kit.


- Suspension kit: Wheel supplied in suspension kit has an eyelet for suspension cable. Connect suspension cable as shown in drawing.
- Placement kit: Wheel supplied in placement kit has tubing clamp. Attach placement tubing as shown in the drawing.



Terminate with Suspension Kit

The suspension kit is used with vertical installations. It consists of a top wheel assembly, shown on the previous page, cable thimbles, cable clamps, and a hook for the top of the casing.

1. Cut the suspension cable to the appropriate length.
2. Attach the cable to the top wheel assembly using the thimble and clamps.
3. Attach the other end of the cable to the chain, as shown in the drawing.
4. Use the chain is used to adjust the final depth of the sensors.




Terminate with Placement Kit

The placement kit is sometimes used with vertical installations. It consists of a top wheel assembly, shown on the previous page, and a “top” clamp for placement tube.

The top clamp holds either placement tubing - when the sensors are deeper in the casing - or the gauge tube of the nearest sensor.

The top clamp has a split collar. Loosen the screws, slide the collar over the placement tubing or gauge tubing, and then tighten the screws.



Horizontal Installation

- Overview**
1. Lay out sensors in order of installation.
 2. Align the first sensor with the vertical grooves of the casing. Insert the sensor with its fixed wheel pointing downwards.
 3. Push the sensor into the casing. Keep the top end of its gauge tubing accessible.
 4. Connect the next sensor to the gauge tubing of the downhole sensor. Then push it into the casing.
 5. Continue connecting sensors until the string is complete.
 6. Connect the final wheel assembly.
 7. Prepare the placement kit and placement tubing.
 8. Push push sensors to final location and terminate.


- Required Tools**
- Safety cable may be useful if sensors are to be retrieved or if casing actually slopes downwards.
 - Vice grips (clamping pliers) for holding gauge tubing while connecting adjacent sensors.
 - Thin 17 mm wrench for tightening tubing clamps.
 - Allen wrench for securing top clamp.
 - Vinyl tape for securing cable to gauge tubing.

- Preparations**
1. Attach gauge tubing to each sensor, as explained previously. We do not recommend joining sensors together now. Add sensors one by one to the string.
 2. Lay out sensors in order of installation. Note the serial number and position of each sensor.
 3. Keep cables coiled until sensor is installed.

- Removal**
- If it is necessary to remove sensors, take the following precautions:
- Never try to remove the assembled string of sensors. The weight and leverage of long gauge lengths make it very easy to damage the wheels.
 4. Always disassemble the string, sensor by sensor. When removing each sensor, always clamp the gauge tubing of the downhole sensor to prevent it from twisting.


Install the First Sensor

1. Check that the first sensor has a swivel clamp on its wheel assembly.
2. Tape signal cable to the gauge tubing.
3. Align the fixed wheel with the bottom groove and push the sensor into the casing.




Install More Sensors

1. Prepare to connect the next sensor. Align the fixed wheel with the bottom groove.
2. Push the tubing clamp into the gauge tubing of the sensor that is already in the casing. Do not twist the gauge tubing when you tighten the tubing clamp nuts.



3. Continue adding sensors until the sensor string is complete.:




- Do not twist the installed sensor when you tighten tubing clamps. Twisting can damage the wheels or pop them out of the grooves.
- Always verify that the fixed wheel is in the bottom groove.
- Tie cables neatly, so that they do not cross each other.

Terminating the Installation

The placement kit supplies most of the components used to terminate horizontal installations. The placement kit includes a top wheel assembly and a top clamp. A top clamp retainer is also available.

Install Top Wheel


The top wheel completes the gauge length of the nearest sensor. Align the fixed wheel with the bottom groove.



The top wheel is not required if the gauge length of the top sensor is terminated with the top clamp.

Install Placement Tubing


Placement tubing is used to position the sensors deeper into the casing. Placement tubing is normally longer than shown in the illustration. A coupling is used to join two placement tubes.



Install Top Clamp

The top clamp holds placement tubing or the gauge tube of the nearest sensor.

1. The top clamp has a split collar. Loosen the screws, slide the collar over the placement tubing or gauge tubing, and then tighten the screw.
2. (Optional) Use the top clamp retainer to hold the top clamp to the casing.



3. In horizontal installations, the sensors normally must be pushed into the casing. This puts the mechanical linkage of the sensors into compression. If possible, put the linkage into tension, but pushing the sensors deeper into the casing and then pulling them back into position.

Manual Readings

Introduction Manual readings are useful for testing the system before the data acquisition system is set up. This manual covers connections to IPI sensors that have a 2.5v signal conditioner. Previous signal conditioners used a 250 mV signal conditioner with different wiring.

- EL Data Recorder**
1. Connect sensor to readout as shown in the table below.
 2. Switch on. Choose uniaxial or biaxial sensor.
 3. Tilt is displayed in volts. Temperature is displayed in degrees C.

| Data Recorder Terminal | Signal Cable Wire |
|------------------------|-------------------|
| 1 Tilt A | Orange |
| 2 Tilt B | Blue |
| 3 Temp | Red |
| 4 Sig Common | Yellow |
| 5 Sense | Violet |
| 6 Power + | Green |
| 7 Power - | Black |
| 8 Shield | Drain Wire |

Testing with a Voltmeter The voltmeter should be capable of displaying values in the low millivolt dc range. You must also have a power source must supply between 5.5 and 15 Vdc. An alkaline 9-volt battery is suitable

1. Connect green wire to the + terminal of the power source. Connect the violet wire and black wire to the - terminal of the power source.
2. To read the A-axis sensor, connect the voltmeter to the orange wire (signal) and yellow wire (reference).
3. To read the B-axis sensor, connect the voltmeter to the blue wire (signal) and yellow wire (reference).
4. To read the thermistor, connect the voltmeter to the red and yellow wires.

Test Readings

1. When the sensor body is vertical, you should see a reading of about 0.0 Vdc.
2. The A-axis sensor measures tilt in the plane of the wheels. Tilt the top of the sensor in the direction of the fixed wheel. The reading should be about 2.2 to 2.3 V as the tilt nears 10 degrees. Tilt the top of the sensor in the direction of the sprung wheel. The reading should be about -2.2 to -2.3 V as the tilt nears 10 degrees.
3. The B-axis sensor (available with biaxial sensors only) is rotated 90 degrees from the A-axis sensor. Tilting the sensor to 10 degrees should provide a reading of ± 2.2 to 2.3 Volts.
4. See the next section, data reduction, to learn how to convert the reading in volts to deviation in mm.
5. At 25 degrees C, the thermistor reading should be about 1 Vdc.

DataLogging


Data Logging with CR10X

These instructions provide information needed for reading uniaxial and biaxial IPIs with the Campbell Scientific CR10X datalogger system.


Sample Program: A sample CR10X monitoring program is available at Slope Indicator's website. Go to www.slopeindicator.com - support - tech notes. Look at the data logger technotes. You'll see a link for sample programs.

Wiring Diagrams: The wiring diagrams on the following pages show how to connect uniaxial and biaxial IPIs to the Campbell Scientific CR10X datalogger system.


Wiring Diagram 1 Connecting a uniaxial sensor directly to the CR10X




Wiring Diagram 2 Connecting a biaxial sensor directly to CR10X



Wiring Diagram 3 Connecting uniaxial sensors to an AM416 multiplexer



Wiring Diagram 4 Connecting biaxial sensors to an AM416 multiplexer



Data Reduction

Introduction Data reduction is usually automated because it involves a large number of readings and a large number of calculations.

Here, we explain how to use the sensor calibration record and provide an example of converting a single reading from voltage to mm of deviation and mm of displacement.

Calibration Record A calibration record is provided with each EL IPI sensor. Note that calibrations are unique for each sensor, so use sensor serial numbers to match sensors with their calibrations.

The sensor calibration record lists three sets of factors for each axis of the sensor and one factor for the temperature sensor. The table at right shows factors for sensor serial number 10001. Your sensors will have different factors.

C0 to C5: Use these factors to convert a reading in volts to mm per meter of gauge length.

S0 to S2: Use these factors if it is necessary to adjust the mm/m value above for temperature-related changes in sensor sensitivity.

F0 to F2: Use these factors if it is necessary to adjust the mm/meter value for temperature-related changes in the offset of the sensor.

Toffset: Use this factor in the equation to convert a thermistor reading in volts to degrees C.

Tnom: Tnom is normally 12 degrees C. However, the value shown on the sensor calibration record may be higher or lower if your sensors were calibrated over a custom range of temperatures.

| | |
|---------|--------------|
| C0 | -7.0311 |
| C1 | 73.878 |
| C2 | -0.22265 |
| C3 | -0.33079 |
| C4 | 0.019426 |
| C5 | 0.020221 |
| | |
| S0 | 1 |
| S1 | 0.00059828 |
| S2 | 0.0000068117 |
| | |
| F0 | 00012125 |
| F1 | 0.016273 |
| F2 | 0.00096919 |
| | |
| Toffset | 0.19 |
| Tnom | 12 |

Applying Calibration Factors

Suppose you obtain a reading of 0.57V from sensor 10001, which has a gauge length of 2 meters. How do you convert the voltage reading to mm of deviation?

Converting sensor readings to mm per meter

Apply the C factors to the voltage reading as shown below. EL represents a reading in volts. C5 through C0 are factors that appear on the sensor calibration record. The result of the calculation is a value in mm per meter.

$$\text{mm/meter} = C5 \cdot \text{EL}^5 + C4 \cdot \text{EL}^4 + C3 \cdot \text{EL}^3 + C2 \cdot \text{EL}^2 + C1 \cdot \text{EL} + C0$$

| | C Factor | EL Reading | Value |
|--------------------------|----------|------------|----------|
| C0 | -7.0311 | | -70311 |
| C1 | 73.878 | 0.57 | 42.11046 |
| C2 | -0.22265 | 0.572 | -0.07234 |
| C3 | -0.33079 | 0.573 | -0.06126 |
| C4 | 0.19426 | 0.574 | 0.002051 |
| C5 | 0.020221 | 0.575 | 0.001217 |
| mm per meter deviation = | | | 34.94903 |

Calculating Deviation

To calculate deviation for a particular gauge, multiply the mm/meter value by the gauge length of the sensor. In this example, the gauge length is 2 meters, so the deviation would be 2 x 34.949 mm or about 70 mm.

$$\text{deviation in mm} = \text{mm per meter value} \cdot \text{gauge length of sensor in meters}$$

In this example, the gauge length is 2 meters, so the deviation would be 2 x 34.949 mm or about 70 mm.

Calculating Displacement


Displacement (movement) is the change in deviation. The next page shows the direction of movement associated with negative and positive displacement values.

$$\text{displacement} = \text{deviation}_{\text{current}} - \text{deviation}_{\text{initial}}$$

Direction of Movement for Vertical IPs

Inclinometer casing is typically installed so that one set of grooves is parallel with the expected direction of movement. Sensors are installed so that their fixed wheels point to the direction of movement.

When the bottom of the casing or the bottom of the sensor is used as reference, positive displacement values indicate movement in the direction of the fixed wheels (normally the expected direction).




**Direction of Movement
Horizontal Sensor**

Horizontal inclinometer casing must be installed with one set of grooves oriented to the vertical. Sensors are installed with the fixed wheel pointing down.


Far-End Reference

When the far end of the casing or the far end of the sensor is used as the reference, negative displacements indicate upward movement and positive displacements indicate downward movement:



Near-End Reference

When the near end of the casing or the near end of the sensor is used as the reference, negative displacements indicate downward movement and positive displacements indicate upward movement:



Temperature Readings

The CR10 delivers thermistor readings in volts. The equation below shows how to convert the volt reading to degrees C. The factors in the equation are optimized for temperatures between -15 and 85 degrees C. ET is the volt reading. Toffset is taken from the sensor calibration sheet.

$$\text{DegC} = (9.3219 \times \text{ET}^5) + (-54.3038 \times \text{ET}^4) + (131.165 \times \text{ET}^3) + (-161.2568 \times \text{ET}^2) + (137.7711 \times \text{ET}) + (-37.7705) - \text{Toffset}$$

Temperature Corrections

If the temperature of the sensors remains relatively constant, as is the case for most underground applications, temperature corrections may not be useful. However, if the sensors experience wide variations in temperatures, temperature corrections may be necessary. There are two corrections: a sensitivity correction called SENSTC and an offset correction OFFSTC.

1. Find the change in temperature from Tnom, which is a value on the sensor calibration sheet.

$$\text{DeltaT} = \text{DegC} - \text{Tnom}$$

Example: DegC is 19.3 and Tnom is 12 degrees C, so DeltaT, the change in temperature, is 7.3 degrees C

2. Calculate the sensitivity correction:

$$\text{SENSTC} = \text{S2} \cdot \text{DeltaT}^2 + \text{S1} \cdot \text{DeltaT} + \text{S0}$$

| | S Factor | DeltaT | Value |
|----------|--------------|------------------|----------|
| S0 | 1 | | 1 |
| S1 | 0.00059828 | 7.3 | 0.004367 |
| S2 | 0.0000068117 | 7.3 ² | 0.000363 |
| SENSTC = | | | 1.00473 |

3. Calculate the offset correction:

$$\text{OFFSTC} = \text{F2} \cdot \text{DeltaT}^2 + \text{F1} \cdot \text{DeltaT} + \text{F0}$$

| | F Factor | DeltaT | Value |
|----------|------------|------------------|----------|
| F0 | 0.00012125 | | .000121 |
| F1 | 0.016273 | 7.3 | 0.118793 |
| F2 | 0.00096919 | 7.3 ² | 0.051648 |
| OFFSTC = | | | 0.170562 |

4. Apply the corrections:

$$\begin{aligned} \text{corrected value} &= (\text{mm/meter value} \cdot \text{SENSTC}) + \text{OFFSTC} \\ &= (34.94903 \cdot 1.00473) + 0.170562 \\ &= 35.28491 \end{aligned}$$

Removing Sensors

Removal of Sensors

If it is necessary to remove sensors, take the following precautions:

- Never try to remove the assembled string of sensors. The weight and leverage of long gauge lengths make it very easy to damage the wheels.
- You must disassemble the string as you withdraw it, so that you actually remove sensors one by one. When removing each sensor, always clamp the gauge tubing of the downhole sensor to prevent it from twisting.