Water Level Meter
with
Laser-Marked Cable

DURHAM GEO SLOPE INDICATOR

Detect LED:
• Illuminates when probe comes into contact with water.
• Flashes every three seconds to indicate WLM is powered on.

Up and Down Buttons:
• Controls WLM sensitivity.
• 9 = High sensitivity
• 1= Low sensitivity

On / Off Button:
• Unit does not power off automatically.

Push-to-Test Button:
• Tests buzzer, LED and display.

Battery Access:
• Remove three screws to access the four (4) double 'AA' batteries.

How to Read the Cable:

English-Unit Cables
Divisions are 0.01 foot. Numerals mark feet and tenths of feet.

Metric-Unit Cables
Centimeters are numbered. Numerals also serve as 2 mm graduations. Centimeter marks are crossed with 1,2, or 3 lines at 100, 200, and 300 m.



Cleaning the WLM

• **Probe:** Wash the probe with detergent.
• **Reel:** Wipe off the reel with a damp cloth. Do not immerse in water.
• **Cable:** Wash the cable with a laboratory detergent such as Alconox or Liquinox. Rinse with distilled water. Remove oily deposits with dish-washing detergent. Do not leave the cable immersed in detergent for a long time. Rinse in distilled water.

pn# 602673 rev. 2.1

Water Level Meter
with
Laser-Marked Cable

DURHAM GEO SLOPE INDICATOR

Detect LED:
• Illuminates when probe comes into contact with water.
• Flashes every three seconds to indicate WLM is powered on.

Up and Down Buttons:
• Controls WLM sensitivity.
• 9 = High sensitivity
• 1= Low sensitivity

On / Off Button:
• Unit does not power off automatically.

Push-to-Test Button:
• Tests buzzer, LED and display.

Battery Access:
• Remove three screws to access the four (4) double 'AA' batteries.

How to Read the Cable:

English-Unit Cables
Divisions are 0.01 foot. Numerals mark feet and tenths of feet.

Metric-Unit Cables
Centimeters are numbered. Numerals also serve as 2 mm graduations. Centimeter marks are crossed with 1,2, or 3 lines at 100, 200, and 300 m.



Cleaning the WLM

• **Probe:** Wash the probe with detergent.
• **Reel:** Wipe off the reel with a damp cloth. Do not immerse in water.
• **Cable:** Wash the cable with a laboratory detergent such as Alconox or Liquinox. Rinse with distilled water. Remove oily deposits with dish-washing detergent. Do not leave the cable immersed in detergent for a long time. Rinse in distilled water.

pn# 602673 rev. 2.0